

FARGO® Workbench

Release Notes

Version: 3.2.2.42
PLT-06209, A.0
October 2021

Copyright

© 2021 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, DTC, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
October 2021	Release notes for version 3.2.2.42.	A.0

A complete list of revisions is available in [Revision history](#).

1.1 Scope

These release notes provide information on the FARGO® Workbench version 3.2.2.42. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 Resolved issues

- Resolved an issue where the Decrypt Secure ID functionality was not working in versions 3.2.1.1 and 3.2.1.13. (FI#9761)
- Resolved an issue where the Device Settings self-test for the DTC®1500 printer model was printing a gray card instead. (DTC1500-301)
- Resolved an issue where a magnetic stripe encoded with a "''" (grave accent) character was being decoded incorrectly. (SIPS-830)
- Resolved an issue where printers could show as offline at times even though they were actually online and available. (SICPI-937)
- Resolved an issue where the English help was not loading as intended when running FARGO® Workbench in the Indonesian language. (SIPS-1020)

1.3 Deprecating functionality

- Removed the Swift ID functionality due to Microsoft removing support for Adobe Flash Player. (FI#12830/SICPI-940)
- Removed the automatic refresh of the printer list after launching the application due to it being very distracting for users. (SIPS-1015)

Revision history

Date	Description	Revision
October 2021	Release notes for version 3.2.2.42.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2021 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-06209, Rev. A.0

Part of ASSA ABLOY